

May 2014 Releases

10.3317 MAP Sensor

Subaru: 22627-AA430

Forester III 2.0D 09/08>
Forester IV 2.0D 08/12>

Impreza III 2.0D 4x4 01/09>
Impreza III 2.0D 01/09>

Legacy IV 2.0D 02/08>
Legacy V 2.0D 05/09>

Outback III 2.0D 09/08>09/09
Outback IV 2.0D 09/09>
EJ20Z engines

9.6348 Coil

Volvo: 30713416, 9125601

C70 I 2.0T, 2.3, 2.3T5, 2.4, 2.4T, 2.5, 2.5T
S60 I 2.0T, 2.4, 2.4 bifuel & T5, 2.5, 2.5T
S70 2.0, 2.0T, 2.3, 2.3T5, 2.4, 2.4 bifuel & blue fuel
2.4 T5, 2.4T, 2.5 & bifuel.
S80 I 2.0T, 2.3R, 2.4, 2.4 bifuel, 2.4 T5, 2.5T, 2.8
T6, 2.9, 3.0, 3.0 T6,

V70 I : 2.0, 2.0T, 2.3, 2.3 T-5, 2.4, 2.4 bifuel &
Turbo, 2.5, 2.5 T

V70 II: 2.0T, 2.3, 2.3 T-5, 2.4, 2.4 Bifuel & turbo,
2.5T

XC90 2.5, T6
XC70 2.3, 2.4, 2.5 turbo Cross Country.
C30 T5
VC70 III R2.5Y AWD, 2.5T & flexifuel.

9.6378 Coil

Ford: 1371601. 6M5G-12029-AA
Volvo: 30713417, 8677837.

Ford: Focus II 2.5Rs 01/09>, 2.5 ST 10/05>
Galaxy II 2.5 ST 05/06>
Kuga I 2.5 03/09>
Mondeo III 2.5 03/07>
S-Max 2.5 ST 05/06>

Volvo: C30 T5.
C70 II 2.14, 2.4i, T5
S40 II 2.4, T5, inc AWD
S60 I 2.0T, 2.4, 2.5, R2.5T
S60 II 2.5 T5
S80 I 2.0T, 2.4 LTP
S80 II 2.5T & flexifuel
V50 2.4 & T5
V70 II 2.0T, 2.4, 2.4 T5, 2.5R, 2.5 flexifuel
XC70 Cross Country 2.4T 01/05 to 12/06.

