











Part Number	OE Equivalent	Application	
<b>9.6007</b> – dry coil	Renault: 77 01 031 135 Volvo: 3287677-3	Renault: 18,19,21,25, Clio, Espace, Express, Laguna, Megane 1.4i Safrane & Traffic. Volvo: 340, 360 84-89. 440, 460 & 480 88>	
<b>9.6046</b> – dry coil	Alfa: 60805420, 60809492 Fiat: 46543562, 46548037 : 7626232, 7672018	Alfa: 155 2.0i Turbo 02/92- 04/96 Fiat: Cinquecento, Coupe, Doblo, Palio, Panda, Punto, Seicento, Siena, Tempra & Tipo 1.8, Uno 1.0ie	
<b>9.6062S</b> – dry coil	BMW: 12131317232, 12131404102 : 12131727108, 12131730766 : 12131734468, 12139066468	BMW: 318is & Coupe, 320i & 325i, Cabrio & Coupe, 520i, 525i, 530i, 540i & Touring, M3 3.0i & 3.2i, M5 3.8i 24v	
<b>9.6069</b> – dry coil	Ford: 6 077 429, 79BB12024AA Motorcraft: EDG 27	Ford: Escort 1.3, 80-86 1.4, 86-89 1.4i 87> 1.6 80-89, 2.0i Cosworth 92> & RS. Fiesta 1.3, 1.4, 1.4i. Orion, Sierra, Transit 2.0i	
			
<b>9.6007</b>	<b>9.6046</b>	<b>9.6062s</b>	<b>9.6069.</b>
<b>9.6088</b> – dry coil	Citroen/ Peugeot: 5970 48, 5970 70 Fiat: 9607405480, 9622889780	Citroen: Berlingo, BX, Evasion, Saxo, Xantia, Xsara, ZX. Fiat: Ducato 2.0ie 03/94> Ulysse 1.8 & 2.0i & Turbo. Peugeot: 106, 205 1.6i, 306, 309 1.6i, 405, 406,605, 806, Partner.	
<b>9.6089</b> – dry coil	Citroen/ Peugeot: 5970 49 Rover: GCL204, GCL302	Citroen: AX 1.1, 1.4i 93> ZX 1.1, 1.4i 91> Peugeot: 106, 205, 306, 405 Rover: 420, 620, 820 2.0i 16v, Mini MPI 1998> vin 134456>	
<b>9.6114</b> – dry coil	Honda: 30510-P73-A01/02/ PT2-006 Rover: GCL 195	Honda: Accord, Civic 1.6 90-91, 1.8i 11/98> Prelude 10/91-12/96 Rover: 416 16v 95> 618, 620 & 623 1993>	
			
<b>9.6088</b>	<b>9.6089</b>	<b>9.6114</b>	
<b>9.6172</b> – dry coil	GM: 90 458 250 Opel: 12 08 071	Vauxhall: Astra 1.8i, 1.8i / 2.0i 16v. Calibra & Omega 2.0i 94> : Vectra 1.8i 16v 09/95-12/98 & 2.0i 16v 08/92>	
<b>9.6199</b> – dry coil	Ford: 6 860 288	Escort, Fiesta 92>. Focus 98>. Mondeo 93>.	
<b>9.6274</b> – dry coil	Rover: GCL201	214i 01/96>. 214/ 414 16v. 1995> 216/ 416 16v 1995>	
			
<b>9.6172</b>	<b>9.6199</b>	<b>9.6274</b>	