

March 2014 Releases

10.4040 air Temp Sensor

VWGroup: 03P 906 081

Seat: Ibiza IV, 1.2TDi 04/10> Sportcoupe 05/10>

Skoda: Fabia II, 1.2 TDi 03/10>, Roomster 1.2 TDi

VW: Polo V 1.2 TDi 10/09> all with CFWA eng.



7.1188 Brake Light Switch

Ford: 6992957, 95FB-7C534-AA

Ford: Escort IV; 1.3, 1.4, 1.4i, 1.6 & 16v, 1.8 16v, 1.8D, RS2000, Cosworth, Fiesta IV; 1.0i, 1.25i, 1.3i, 1.4i, 1.6 16v, 1.8D/Di Ikon: 1.3 EFI & Rocam, 1.6 EFI Rocam, 1.8D KA: I 1.3 & 1.6i Orion III; 1.3/1.4 Puma: 1.4i/1.6i/1.7i Street KA; 1.6.




7.1300 Brake Light Switch

Hyundai/ Kia: 93810-2E000, 93810-38000,

Kia: Coupe II 1.6/2.0/2.7 V6, Elantra & III 1.6/1.8/2.0, IV 1.6/2.0 CVT. H-1, H100, i10 1.0/1.1 CRDi, i20 1.2/1.4 CRDi, 1.6, i30 1.4/1.6/2.0, i40 1.6GDi, Lantra II 1.6/1.8, Libero, Matrix, Porter, Sonata IV/V, Trajet 2.0/CRDi/2.7, Tucson, XG25, XG30/300, XG350

Hyundai: Bongo III, Carnival II 2.2/2.7/2.9. CEED 1.6/1.6 & CVT, 2.0. Cerato 1.5, 1.6, 2.0 7 CRdi & II 1.6 & 2.0. Magentis I & II. Optima II, Picanto I. Pro CEED Rio III. Soul. Sportage II.



7.3368 Water Temp Sender

Daihatsu: 89422-16010-000. Ford: 1448377, 6M34-12A648-AA. Honda: 37870-P7A-005. Mazda: KLK1-18-840. Suzuki: 13650-50F10-000, 13650-50G10-000, 13650-M50G20. Toyota: 89422-16010, 89422-22030

Daihatsu: YRV 1.3/FWD 02/01>.

Ford: Endeavour 2.5/3.0 TDHi, Everest 3.0, Ranger IV 2.5/3.0 TDHi

Honda: LOGO 1.3 99>02.

Mazda: 323: CV, FV, FV1, PV, PV1, SV, SV1. 626 V 2.0T, BT-50, Demio 1.3i. MPV II, MX-5 II. Protege.

Suzuki: Alto IV, Ignis 1.3 02>08, Jimny, Wagon-R

Toyota: Camry V 2.0/2.4 WTi, Corolla VIII 1.4/1.6/2.0D Echo 1.5. Paeso 1.5. Picnic 2.0. Starlet 1.3. Yaris I 1.0/1.3 16v/1.4d-4D, 1.5TS, 1.5 VVI-TS. & Verso.



7.3376 Water Temp Sender

VWGroup: 038 906 081B

Audi: A3 II 1.9 TDi 05/03> BLS, BXE eng.

A3 III Sportback 1.9 TDi 09/04>05/10.

A4 IV 3.0 TDi Quattro 11/07> CAPA eng.

