

Sept 2013 Releases

10.3098 MAP Sensor

Kia/Hyundai: 39300-22600, 39300-38110, 39300-38120

Hyu: Accent 2/3/4, Atos 1.0/1.1, Coupe 1/2, Elantra 3 & 4(2.0 CVT), Getz, i10, 130, Lantra 2, Lavita, Matrix, Santa Fe, Sonata IV, Trajet, Tucson 2.0, Verna.
Kia: Ceed I 2.0, Cerato, Magentis 2.0, Picanto 1.0/1.1, Pro Ceed 2.0, Rio II 1.4/1.6 16v



10.3118 MAP Sensor

Kia/Hyundai: 39300-38100, 39300-38200

Hyu: Centennial 3.5/3.8, Equus, Genesis 3.8 V6, Grandeur, H-1, ix55 3.8 V5, Santa Fe I & II, Sonata 4;.4 16v & 5 : 3.3, Starex, Terracan, XG.
Kia: Carnival II 2.7 V5, Magentis I/2, Opirus, Sorento I 2.4, 3.3, 3.5 V6.



10.3131 MAP Sensor

Kia/Hyundai: 39200-27400, 39200-42020, 39200-42030.

Hyu: Genesis Coupe 2.0T, H-1 Autobus 2.5Td, H100, Libero 2.5TCI, Matrix 1.5 CRDi, Porter, Starex, Terracan 2.5 D/TD.
Kia: Cerato 1.5 CRDi 07/05>, K2500, Pregio 2.5 TCI.



10.3178 MAP Sensor

Kia/Hyundai: 39300-2G000, 39300-84400

Hyu: Accent II, Getz 1.5CRDi, H-1, H100, i10, i20, i30 I/II, i40 1.7CRDi, ix20, ix35, ix55, Matrix, Santa Fe, SB11, Sonata, Starex, Tucson, Velosteer, Verna.

Kia: Carens II 2.0, III 1.6/2.0 CRDi, Ceed I/II, Cerato, Optima, Picanto I, Pro Ceed, Rio, Sorento, Sportage 2/3.



10.3179 MAP Sensor

Hyundai: 39200-27000

Hyundai: Genesis Coupe 2.0T 01/08>, Santa Fe I 2.0 CRDi & 4x4, Trajet 2.0 CRDi 9D4EA eng.)



9.0552 Timing Sensor

Seat, Skoda, VW: 036 906 433B

Audi: A3 II & Sportback 1.9/2.0 TDi.

Seat: Altea 1.9 TDi 04/04>, Leon II 1.9 TDi, Toledo III 1.9 TDi 10/04>05/09, Octavia II, Superb II (BXE)

VW: Golf V 1.4 16v, 1.6 FSi, 1.9/2.0 TDi, Golf VI 2.0 TDi, Polo IV 1.4/1.6, Touran 1.6 FSi, 1.9/2.0 TDi.




9.6482 Coil

Hyu/ Kia : 27310-22600

Hyu: Accent 2,3,4, Coupe II 1.6, Elantra III 1.6, Getz 1.3,1.4,1.6, Lantra II, Lavita, Matrix, Verna.

Kia: Cerato I 1.6, Rio II 1.4/1.6 (G4ED/EE eng)



further New Releases for Sept 2013.

Thermostats :

7.8736	7.8773	7.8774
7.8798	7.8805	7.8823
7.8841		