

Autumn releases.

10.3085 MAP Sensor

Skoda: 047 906 051.
Felicia I & II 1.3, AMG & AMH engine.



10.3086 MAP Sensor

FORD: 1110963. YS6A-479-AA
Fiesta IV 1.25i 16V 08/95>01/02, 1.4i 16v
04/96> 01/02



10.3087 MAP Sensor

BMW: 0872 648. L.Rover: MHK100820L
Mini: 12140872648. Rover: MHK100820.



10.3088 MAP Sensor

Chrysler: 5269565, 5293985AA.
Cirrus 2.0i 16v, Neon 1.8 & 2.0 16v, Sebring 2.0.



10.3089 MAP Sensor

SAAB: 9197948.
9-3 & 9-5 series, 2.0/2.3/3.0 Turbo. B204,205, 235,
308 engines.



10.3125 MAP Sensor

BMW: 0872679 Rover: MHK101040.
Mini: Cabriolet, Cooper, Cooper S & Works. Rover:
75 1.8 Turbo.



9.0449 Timing Sensor

Fiat: 71739799 GM: 24435096, 25337265.
Fiat: Stilo 1.6 16v PDA. GM: Astra G & H, Meriva,
Vectra C, Zafira. Z16XEP engine.



9.0493 Timing Sensor

GM: 90486211.
Astra F, Corsa B, Tigra. 1.4 & 1.6i various.



9.0494 Timing Sensor

Hyundai: 39180-4A111
Sorento 2.5 CRDi 08/02>



For full application details [click here](#) to request our CD Rom
OE Part numbers used for reference purposes only
For details of our full range visit our website: www.capricorncarparts.com