

New! 'Direct Fit'

10.8068 Lambda Sensor

Citroen: 1618 R0, 9657632980 Peugeot: 1618 R0



Applications

Berlingo 1.4 bivalent 11/02 & 04/03> C2
1.4 KFV TU3JP 09/03>
206 1.4 K6D, KFW, TU3AF 04/05>
207 1.4 KFV 02/09>
1007 1.4 KFW 04/05>
Partner 1.4 KFW 04/05>
Ranch 1.4 KFW 04/05>

10.8069 Lambda Sensor

Peugeot: 1618 72



Applications

Peugeot 407 1.8 6FZ (EW7J4) 05/04>

10.8078 Lambda Sensor

MINI: 1178 7548961, 7548 961 Peugeot: 1618 V3



Applications

MINI Cooper N12B16A 10/06>
MINI Cooper S N14B16A 10/06>

Peugeot 207 1.6 16V 5FW 02/06>
207 1.6 16V Turbo 5FX 02/06>

10.8083 Lambda Sensor

Volkswagen: 03C 906 262P, 03C 906 262R



Applications

Golf 5, 1.4 FSI BMY 05/09>
Golf 5, 1.4 TSI BLG, BMY 06/07>
Golf 5 Plus 1.4 FSI 05/06>
Golf 5 Plus 1.4 TSI 05/06>
Jetta 1.4 TSI BLG, BMG 07/06>
Touran 1.4 FSI BLG 11/06>

10.8087 Lambda Sensor

BMW: 1178 3413 464, 3413 464. Bosch: 0258 005 337.



Applications

BMW X3 2.5i M54256S5 01/04>
BMW X3 3.0i M54306S3 01/04>

10.8093 Lambda Sensor

Denso: 234 000-9092, Suzuki: 18213-54D00-000, 18213-54D01-000



Applications

Suzuki Alto 4, 1.1 06/02>
Cary 1.3 G13B 03/99>
Cary 1.3 16V G13BB 03/00>

****NB: Initial availability from 25th Sept onwards - subject to confirmation.****

For more details, request our New Products 2008 Brochure FA-NP08

OE Part numbers used for reference purposes only

For details of our full range visit our website: www.capricorncarparts.com